SERVICE INFORMATION

Doc_000138_en

11.04.2023

FIRMWARE UPDATE FILE SMARTBOARD (COMPATIBLE WITH TEBS E3)

This document is providing step by step instructions for updating the new SmartBoard to enable compatibility with TEBS E3 Standard, Premium and Multivoltage modulators.



UPDATING THE SMARTBOARD

1. Download the update file from below link:

Firmware update file Smartboard II (compatible with TEBSE3)

- 2. Extract the file and save the file "SBII_SB020140_dpl2.hex" on your computer.
- 3. Open the SmartBoard Diagnostic Software and go to the tab "SYSTEM":





SERVICE INFORMATION

Doc_000138_en

11.04.2023

4. Click on "ECU update":



5. Click on "READ FROM FILE" and select the downloaded file:

+ ma	802 update		7, 0 1
O foliation	BC/ data		
200 update Dears that the supply voltage is not instituted all society the dearcticus. The voltage should be greans that 201: The connection of the diagnosis to the dealcovic system must not be interruged.	5-8 ED0.	Sectores	
	Daring samples	440,902,940,0	
	Partners services	1354564	
	Secial-sumber (ED):	HOURS	
	Sillian pet santat	Adda and class ()	
	Elignatic protection that	8	
	Dominant File		
NASTRONING STAT			
1000 (1100)			
			× .
The second strategy and second			



SERVICE INFORMATION

Doc_000138_en

11.04.2023

6. Click on "WRITE TO ECU":

6- Helt	BCU update		= 0 1
Instruction			
ICD update finant that the supply rollage is not restricted of during the description. The voltage decould be grower than (if it the screenflue of the diagnosis to the sheftware system must not it is interrugited.	Area 104	Seattlead 9	
	Device lumber	446-192.219 E	
	Partners (million)	104864	
	Sent-unite (SDA	INO-COLINI)	
	Tollower part transfers	364 001 008 2	
	Cuprate potential loaf	1	
	Described File 180, 0800718, opt	ie 1	
NEAD-TREAM FILE	Copyreprese March 1990 (National Not Aurean 2011) TELSTON Participants in manufactors National Not National Laboration Not National		i
9817 304C0	Techner Sera Number Benided Station Street Benided		
			× 8
and weather an equity was seen			

7. After the process is completed, click "OK":

+ 10		RCM applate	7,0	
O Instruction	RCI ana			
BUV applicited linears that the supply unlenge is not another all during the distortion. The willarge should be growner that 20%. The interaction of the disposite the the alchieves optimes must not be been update.	Artisa IGE	StarState 1		
	Darlie Autom	446. Mil 210/2		
	Partner of the	10404		
		SCV update		
	-	*		
	Die V Download com	Ba V Downad complete. Switch geton of and on again Diagnosis and temporate. Preserve endacion diagnostic commerciani		
General Jospen 1818.	1964			
8				
-	Transverse Market (1998) Research Fact Southern (1987) 1983	1		
and the set	The Austral Face Name Section 2014			
			4	
I THE REAL PROPERTY AND INCOME.			14	

- 8. Switch ignition off and on again.
- 9. Re-establish diagnostic connection.
 - ⇒ The update is finished.

An update via the TEBS E diagnostic software is also possible and requires your TEBS E PIN 2.

