

461 491 ... 0 Variant Abwandlung Variante Variante Variante	Test step ♦ Prüfschritt ♦ Paso de control ♦ Étape de contrôle ♦ Passo di controllo											
	3. + 4. + 7.5 + 8.			7.1			7.2 + 7.3			7.4		
	H1 mm	P1 bar	P2 bar	H2 mm	P3 bar	P4 bar	H3 mm	P5 bar	P6 bar	H4 mm	P7 bar	P8 bar
017	on request											
100 102	34,6 +4,5 -3,5	7	7	5,7 +1,7 -1	0,01...0,2	0,01...0,2	17,2±2,7	3	2,75...3	24±3	7	6,75...7
104	on request											
121	on request											
137	on request											
145	on request											
149	44 +5 -5	7	7	7,2 +2,2 -1,3	0,01...0,25	0,01...0,2	21,5±3,4	3	2,75...3	29,9±3,7	7	6,75...7
152	on request											
158	=> 100											
200	35,2 +4,5 -3,5	7	7	5,7 +1,7 -1	0,01...0,25	0	20,5±3,2	3	2,6±0,1	25,5±3,2	7	7 minus predominance 7 minus Voreilung 7 menos predominancia 7 meno predominanza 7 moins prédominance
250	on request											
254	on request											
270	on request											
273	on request											
274	34,6 +4,5 -3,5	7	7	5,7 +1,7 -1	0,01...0,2	0...0,05	20,5±3,2		2,7...2,85	25,5±3,2	7	6,7...6,85
345	on request											